

Waterbody Subsegment Code	Waterbody description	Suspected Causes on October 29, 1999, Court Ordered 303(d) List.	Reason for not including on Modified Court Ordered 303(d) List (February 29, 2000)
050101	Bayou Des Cannes - Headwaters to Mermentau River	Copper	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
050201	Bayou Plaquemine Brule - Headwaters to Bayou Des Cannes	Lead	New data shows it is meeting WQS
		Phosphorus	New data shows it is meeting WQS
		Turbidity	New data shows it is meeting WQS
050301	Bayou Nezpique - Headwaters to Mermentau River	Copper	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
050401	Mermentau River - Origin to Lake Arthur	Phosphorus	Assessment of data shows it is meeting WQS
		Copper	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
		Mercury	New data shows it is meeting WQS
		Suspended solids	New data shows it is meeting WQS
050501	Bayou Queue de Tortue - Headwaters to Mermentau River	Lead	New data shows it is meeting WQS
050601	Lacassine Bayou - Headwaters to Intracoastal Waterway	Phosphorus	Assessment of data shows it is meeting WQS
		Suspended solids	New data shows it is meeting WQS
		Turbidity	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
050703	White Lake	Siltation	Assessment of data and inform. shows it is meeting WQS
		Turbidity	Assessment of data and inform. shows it is meeting WQS
		Lead	New data shows it is meeting WQS
050801	Mermentau River - Catfish Point Control Structure to Gulf of Mexico (Estuarine)	Copper	New data shows it is meeting WQS
060101	Spring Creek - Headwaters to Cocodrie Lake (Scenic)	Siltation	Assessment of data shows it is meeting WQS
		Turbidity	New data shows it is meeting WQS
		Cadmium	New data shows it is meeting WQS
		Copper	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
		Mercury	New data shows it is meeting WQS
060102	Cocodrie Lake	Cadmium	Original basis for listing determined to be inaccurate
		Copper	Original basis for listing determined to be inaccurate
		Lead	Original basis for listing determined to be inaccurate
060201	Bayou Cocodrie - From U.S. Hwy. 167 to the Bayou Boeuf - Cocodrie Diversion Canal (Scenic)	Lead	New data shows it is meeting WQS
060203	Chicot Lake	Copper	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
060204	Bayou Courtableau - Origin to West Atchafalaya Borrow Pit Canal	Lead	New data shows it is meeting WQS
060205	Bayou Teche - Headwaters at Bayou Courtableau to I-10	Lead	New data shows it is meeting WQS
060401	Bayou Teche - Keystone Locks and Dam to Charenton Canal	Phosphorus	Assessment of data shows it is meeting WQS
060501	Bayou Teche - Charenton Canal to Wax Lake Outlet	Phosphorus	Assessment of data shows it is meeting WQS
060702	Lake Fausse Point and Dauterive Lake	Phosphorus	Assessment of data shows it is meeting WQS
060801	Vermilion River - Headwaters at Bayou Fusilier-Bourbeaux junction to New Flanders (Ambassador Caffery) Bridge, La. Hwv. 3073	Phosphorus	Assessment of data shows it is meeting WQS
		Cadmium	New data shows it is meeting WQS
		Lead	New data shows it is meeting WQS

Waterbody Subsegment Code	Waterbody description	Suspected Causes on October 29, 1999, Court Ordered 303(d) List.	Reason for not including on Modified Court Ordered 303(d) List (February 29, 2000)
060802	Vermilion River - From New Flanders (Ambassador Caffery) Bridge, La. Hwy. 3073 to Intracoastal Waterway	Phosphorus	Assessment of data shows it is meeting WQS
		Lead	New data shows it is meeting WQS
060902	Bayou Carlin (Delcambre Canal) - Lake Peigneur to Bayou Petite Anse (Estuarine)	Copper	New data shows it is meeting WQS
061104	Vermilion Bay	Copper	New data shows it is meeting WQS
090101	Pearl River	Copper	New data shows it is meeting WQS
090202	West Pearl River	Copper	New data shows it is meeting WQS
110507	Bayou Anacoco	Dioxin	Original basis for listing determined to be inaccurate, dioxin included with priority organics listing